

Cables, Controls & Gauges

- 1) WIPER SWITCH REPLACEMENT UP TO 1974 155495/X
- 2) BULB GLB281
- 3) WIPER WARNING LIGHT 159894
- 4) BULB GLB987
- 5) TURN SIGNAL LENS REPLACEMENT 158917/X
- 6) WIPER KNOB 725374
- 7) TACHOMETER CABLE 71-74 138316
- 8) CABLE GROMMET 600396
- 9) HAZARD SWITCH UP TO 1974 39976
- 10) TACHOMETER 1973 - 1974 218835
- 10) TACHOMETER 1975 - 1980 TKC1706
- 11) HAZARD SWITCH 1975 - 1977 30982
- 11) HAZARD SWITCH from FM60,006 UKC8204
- 11) HAZARD SWITCH KNOB 1975 - 1980 54329399
- 12) HAZARD SWITCH BULB from 1975 GLB281
- 13) SPEEDOMETER (SNT6211-12SB) TKC1515
- 14) VOLTAGE STABILIZER 148876
- 15) SPEEDO CABLE NON O/D 71-74 156316
- 15) SPEEDO CABLE O/D 71-74 156318
- 15) SPEEDO CABLE 1975-1980 NON O/D GSD410
- 15) SPEEDO CABLE 1975-1980 O/D GSD273
- 16) SPEEDO RESET CABLE 159737
- 17) CHOKE CABLE GROMMET 61917
- 18) CHOKE CABLE WITH KNOB 518313/4
- 19) CHOKE KNOB UKC2673
- 20) FUEL GAUGE 1973 - 1980 159604

- 21) WARNING LIGHT 158496
- 22) MAIN LIGHT SWITCH 30731
- 23) TEMPERATURE GAUGE 159606
- 23) TEMP / OIL PRESSURE GAUGE WITH TEMP FIT BHA4900
- TEMPERATURE ADAPTER FOR ABOVE GAUGE 11K2846
- 24) INSTRUMENT BULB (screw type) GLB987
- 25) WARNING LIGHT LENS 159893
- 26) WARNING LIGHT LENS USED 148830USEI
- 27) DIMMER SWITCH 150620
- 28) MAP LIGHT UKC3946

Map Light

